

Image Reverse



Disable



Enable

URL Code



OFF



ON

2D WIRED
BARCODE SCANNER
USER MANUAL



Version

Factory Default



If the scanner encounters any of the following issues, please reset it to Factory Default Settings.

- ① The scanned barcode data cannot be transmitted.
- ② No beep sound when scanning barcodes.
- ③ The scanned barcode data does not include a suffix carriage return (Enter).

Suffix



CR(default)



TAB



Disable

Sound Setting



ON



OFF



High



Low

Enable all 1D/2D barcodes



Enable all
1D barcodes



Enable all
2D barcodes